

**AMIAD Water Systems Ltd.**

# ADI-P - Troubleshooting



**Disclaimer:**

Copyright © 2024 Amiad Water Systems Ltd. All rights reserved.

The contents of this document, including without limitation all information and materials, images, illustrations, data, drawings, names and any other such materials that appear in this document are the sole property of Amiad Water Systems Ltd., including any intellectual property rights, whether registered or not, and all know-how contained or embodied therein. Amiad may alter, remove or change the Content without any further notice. You may not reproduce, copy, modify, create derivative works from, sell or participate in any sale of, or exploit in any way, in whole or in part, any of this document or its content.

The confidential nature of and/or privilege in the file enclosed is not waived or lost as a result of a mistake or error in this file. If you received this file in error, please notify Amiad immediately at [info@amiad.com](mailto:info@amiad.com).

This document does not replace any certified drawing, procedure or information provided by Amiad in reference to a specific customer, site or project.

Amiad assumes that all users understand risks involved within this file and/or its attached materials. This document is given in good faith and is not intended to impose any obligation to Amiad. While every effort has been made to ensure the information in this manual is accurate and complete, we would appreciate if you can bring any errors or omissions to the knowledge of Amiad or consult Amiad experts or its authorized representatives if you have any questions.

Amiad Water Systems Ltd. D.N. Galil Elyon 1, 1233500, Israel Tel: 972 4 690 9500 | Fax: 972 4 814 1159 Email: [info@amiad.com](mailto:info@amiad.com)

Version	Content	Author	Date
1.0	Preliminary version	Saar Levinkron	29.10.2023
1.1	Addition: Continuous flush while outlet pressure zero	Saar Levinkron	04.02.2024

## Table of Contents

Introduction.....	4
Controller/Hardware issues.....	5
The controller fails to initiate flushing. ....	5
Valve Issues (Open/Close Problems). ....	5
Controller does not work at all. ....	5
Valves Operating Oppositely (Open instead of Close, Close instead of Open).....	6
Firmware Update Failed.....	6
Sensor failure.....	6
Flushing by interval does not work. ....	7
continuous flush while outlet pressure displays zero.....	7
Mobile app\User interface issues.....	8
Connection Issues.....	8
Controller does not present water pressure.....	8
I cannot see history in mobile App.....	8
I see negative value in my DP reading.....	8
The Controller issues alerts following firmware upgrade.....	8
I get piston error in my ADI-PLT controller.....	8

## Introduction

The ADI-P Filter Backwash Controller is a crucial component of your filtration system, ensuring its efficient operation. This troubleshooting guide aims to assist you in resolving common issues related to the controller, which is controlled via Bluetooth communication and a mobile app.

Please follow the steps below systematically to identify and resolve the problem you are experiencing.

If you have other issues please contact us [adi-p@amiad.com](mailto:adi-p@amiad.com) or via the mobile application support

## Controller/Hardware issues

Problem	Cause	Check	Recommended action
The controller fails to initiate flushing.	Empty or low battery.	Examine the battery status.	Replace batteries.
	Incorrect DP settings.	Inspect the Differential Pressure (DP) across the filtration system.	Adjust DP settings based on water quality and dirt load.
	'Interval flush pause' is ON.	In the ADI-BLE mobile app, go to Technician settings and check 'Interval Flush Pause' status.	If the 'Interval Flush Pause' status is ON, turn it OFF.
	'Action to take in continuous flush' is set to 'Time only'	Check 'Action to take in continuous flush' in the Technician Settings in the ADI-BLE app.	Go to technician settings >> Action to take in continuous flush' >> change from 'Time only to 'Ignore'.
	The controller is set as secondary.	Go to Technician settings and check 'Operation mode' status.	If the 'Operation Mode' status is SECONDARY, Change it to CONTROLLER. Reselect filter type.
	The controller is in 'Pause Mode'	Check 'Controller State' in the Settings in the ADI-BLE app.	If the 'Controller State' status is OFF, change it to ON.
Valve Issues (Open/Close Problems).	Faulty solenoid.	Inspect the solenoid for defects or wiring.	Replace solenoid or repair wiring.
	Clogged control tubes.	Check the control tubes for blockage	Clean the control tubes.
	Faulty flushing valve.	Examine the valve for faults.	Service the valve or replace if needed
Controller does not work at all.	Improper battery insertion or connection	Verify battery placement and connections. Check battery orientation	Reinsert battery correctly. Ensure secure connections.
	Battery damage or age	Inspect battery for damage or age.	Replace damaged/old battery with a compatible one. High quality or industrial grade battery. Our recommendation is to replace the batteries once a year

Valves Operating Oppositely (Open instead of Close, Close instead of Open).	Solenoid polarity reversed	Ensure solenoids are correctly connected	Reverse the solenoid connections polarity
Firmware Update Failed.	Last Firmware version has not been downloaded to the mobile device	Check in the 'About' section that last firmware version has been downloaded	In the ADI-BLE, go to Settings >> About >> check 'Last FOTA Downloaded' date.
	Bluetooth interruption.	Verify Bluetooth connection. Ensure mobile device is close to the controller (few meters) and not disturbed.	Retry firmware update while ensuring constant Bluetooth connection.
Sensor failure.	Loose connection.	Ensure the sensor tube/wire connection is stable.	Tighten the connection
	Sensor malfunction.	Confirm filtration system pressure.	Configure the piston sensor role as an inlet/outlet sensor. Open the mobile app, connect to your controller, and app do the following. Settings >> Technician Settings (password: 1234) >> Sensor Role Config >> Select piston sensor as Inlet or Outlet. Connect the piston sensor to the inlet/outlet tube.  This requires FW version 1.4.6 or newer
	Excessive negative pressure in the filtration system	Check water pressure in the system with external pressure stat	install anti vacuum valve at the inlet

Flushing by interval does not work.	Interval flush pause is ON.	Go to Technician settings and check 'Interval Flush Pause' status.	If the 'Interval Flush Pause' status is ON, turn it OFF.
continuous flush while outlet pressure displays zero			<ol style="list-style-type: none"> <li>1. Reset to factory settings: Click on restore to factory settings in the settings screen.</li> <li>2. Go to settings and click on Technician setting.</li> <li>3. Insert the password: 1234</li> <li>4. Click on Filter type.</li> <li>5. Select a different filter type than currently configured.</li> <li>6. Click on the V to save:</li> <li>7. Reenter to filter type settings, select the desired filter type and click on the V to save.</li> </ol>

## Mobile app\User interface issues

Problem	Cause	Check	Recommended action
Connection Issues.	Bluetooth disabled. Bluetooth out of range.	Ensure Bluetooth range. Move closer to the controller to establish a Bluetooth connection	Enable Bluetooth on mobile device. Restart device - reinsert one battery.
	Mobile app Malfunction.	Reset mobile app.	Exit and enter the mobile app. Reinstall app - unload and redownload the mobile app.
	Other user is connected to this controller.	Check that no one else is connected to the controller.	Reset device (disconnect power/reinsert batteries) or disconnect other User.
	Outdated mobile device operating system.		Update mobile device operating system version.
Controller does not present water pressure.	The controller is set as secondary.	Go to Technician settings and check 'Operation mode' status.	If the 'Operation Mode' status is SECONDARY, Change it to CONTROLLER. Reselect filter type
I cannot see history in mobile App	Known issue in older versions	Check for the latest ADI-BLE version on Apple store/Google store. Check for FW version to be 1.4.6 or newer	Update controller's firmware if required
I see negative value in my DP reading	tubes may have been connected opposite	Check tubes connection polarity to confirm not opposite	Connect tubes in the right direction for inlet/outlet
The Controller issues alerts following firmware upgrade	Filter type configuration might be erased	Check filter type configuration	Go to settings >> Click 'Restore to Filter Type Settings'.
I get piston error in my ADI-PLT controller	The default filter type configuration has the piston sensor enabled.	Check filter type configuration	Reinsert battery and then select a filter type with piston sensor disabled such as 'Mini-Sigma 2 PS'